ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	8	Kodigehalli

Street ID	Street Name	Significant Landmark
W0292, W0290, W0280, W0286, W0288, W0383, W0375, W	3rd Crs Lakshmi Sagar Lyt, NA, 2nd Crs, Lakshmi Sagar Lyt, 4th Crs, Maheshwari Nagar, 1st Crs, 6th	MARUTHINAGAR AND BB NAGAR

Segment No.	Total Length (m)
8/C-W0292/S101834	617.33

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	63.58	77.580933	13.058183	77.581398	13.057941	W0375	W0383
2	59.92	77.581024	13.058391	77.581562	13.058267	W0375	W0383
3	77.76	77.581102	13.058768	77.580851	13.058112	W0288	RI-A23
4	222.42	77.582054	13.058658	77.583775	13.058134	W0415	RI-A23
5	193.65	77.582072	13.058543	77.583840	13.058306	W0292	W0415

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to roadsdrain and footpath in cross roads of MARUTHINAGAR AND BB NAGAR in Ward no 8 (Kodigehalli) Kodigehalli Sub-Division Yelahanka zone	5000000	2016

Year	Type of Work	Other Work Type
2016 - 2017	Others	Roads Drain and Footpath

Tender	Work Details	Job No. / Work Code
Not a Tender	Improvements to roads drain and footpath in cross roads of MARUTHINAGAR AND BB NAGAR in Ward no 8 (Kodigehalli) Kodigehalli Sub-Division Yelahanka zone	008-17-000002

Work Order No.	Work Order Date	Period of Extention
BBMP/ EE/BTP/WO/142/2016-17	24/10/2016	90 DAYS

Defect Liability Period From	Defect Liability Period To	Multiple road involved with the same Job No/ Work Code #
24/10/2016	23/10/2017	Yes

Contractor Details

Zone: YELAHANKA **Ward No:** 8 **Ward Name:** Kodigehalli **Street ID:** W0292, W0290, W0280, W0286, W0288, W

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
KRIDL		0.00
Phone No.	**E-Mail ID**	
9449863065		

Field Inspection Details

Number of Trees	Any Other Information	Name
6		DHANANJAYA
Date of Inspection	**Remarks**	
13/02/2017	COMPLETED	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 8 **Ward Name:** Kodigehalli **Street ID:** W0292, W0290, W0280, W0286,

Drain Condition		This photo seems out of range..
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	13/02/2017	15/03/2017	COMPLETED
SE	VASU K M	13/02/2017	15/03/2017	COMPLETED
EE	MOHAN DAS HT	13/02/2017	15/03/2017	COMPLETED
AEE	RANGANATH	13/02/2017	15/03/2017	COMPLETED
AE	DHANANAJAYA	13/02/2017	15/03/2017	COMPLETED
AE	DHANANAJAYA	13/02/2017	15/03/2017	COMPLETED

Zone: YELAHANKA **Ward No:** 8 **Ward Name:** Kodigehalli **Street ID:** W0292, W0290, W0280, W0286,